

FORM
43Rev
05/21

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

02/27/2023

Document Number:

403330396

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 17320 Contact Person: Emma Millar
Company Name: CITY & COUNTY OF DENVER Phone: (208) 610-6012
Address: 8500 PENA BLVD AOB 10TH FLOOR Fax: ()
City: DENVER State: CO Zip: 80249-6340 Email: emillar@cottonwoodconsulting.com

Identification Information

API Number: 05 - 001-06829 OGCC Facility ID: 201426 Initial Form 19 or 27 Document number: 403148067
Facility Name: BOX ELDER K Facility Number: 2 Facility Type: WELL
Location QtrQtr: SWNW Section: 6 Township: 2S Range: 65W Meridian:
County: ADAMS Field Name: THIRD CREEK
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CITY & COUNTY OF DENVER Agent Name: Emma Millar Title: Consultant
Phone Number: 208-610-6012 Email: emillar@cottonwoodconsulting.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 201426 Facility Name: BOX ELDER K 2 Facility Type: Oil and Gas Well
Location: QtrQtr: SWNW Sec: 6 Twp: 2S Range: 65W Meridian: 6
County Name: ADAMS Latitude: 39.908900 Longitude: -104.712330

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 107919 Document Name: Size of file in bytes: 32614 File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery
Soil Sample EDD (7).xlsx
SampleType: Matrix:
Facility ID: 201426 Sample ID: 646415 Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Sample Date: 11/14/2022
Collection Point: PRODEQP Matrix: SOIL Pre Post: Remediation
Project Number: Remediation Number: 25348 Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2211209-06

Batch ID: 107916	Document Name: Size of file in bytes: 32630	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (4).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646412	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 11/14/2022
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2211209-03

Batch ID: 107920	Document Name: Size of file in bytes: 32608	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (8).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646416	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 11/14/2022
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2211209-07

Batch ID: 107914	Document Name: Size of file in bytes: 32612	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (2).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646410	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 11/14/2022
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2211209-01

Batch ID: 107921	Document Name: Size of file in bytes: 32082	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (9).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646417	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 12/05/2022
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2212101-01

Batch ID: 107917	Document Name: Size of file in bytes: 32643	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (5).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646413	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 11/14/2022
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2211209-04

Batch ID: 107915	Document Name: Size of file in bytes: 32615	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (3).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646411	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 11/14/2022
Collection Point: SEP	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2211209-02

Batch ID: 107913	Document Name: Size of file in bytes: 32221	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (1).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646409	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 01/05/2023
Collection Point: WellHead	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2301061-01

Batch ID: 107918	Document Name: Size of file in bytes: 32621	File Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery Soil Sample EDD (6).xlsx	
SampleType: _____		Matrix: _____	
Facility ID: 201426	Sample ID: 646414	Sample Name: Box Elder K#2 and Box Elder K #1-3 Tank Battery	Sample Date: 11/14/2022
Collection Point: PRODEQP	Matrix: SOIL	Pre Post: Remediation	
Project Number: _____	Remediation Number: 25348	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.	Lab Sample ID: 2211209-05

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through the COGIS data system.	05/29/2023
Environmental	RTD - Operator request.	02/27/2023
Total: 2 comment(s)		