

**Operator: 8 NORTH LLC**

**Location Name: LARI-611N61W/33NWSW**

**Loc ID: 310705**

**Inspection: 696304943**



**Exhibit A**

**CA:** Stained Soil at Wellhead. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

**CA Resolution:** Operator has reported and provided photo evidence that the identified stained soils have been properly addressed and disposed of to comply with Rule 905.e.