

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 8996 From entrance to location



Photo # 8997 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad
Location ID: 323888



Photo # 8998 Location



Photo # 8999 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 5330 From Inspection 708900277 conducted on 04/13/2023 Meter calibration info not conspicuously posted



Photo # 6929 From Inspection 708900414 conducted on 05/04/2023 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 9000 Meter calibration info not conspicuously posted



Photo # 9001 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 9002 Meter calibration info not conspicuously posted