

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



Photo # 9009 From entrance to location



Photo # 9010 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



Photo # 9011 Location



Photo # 9012 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



**Photo # 4545 From Inspection 708900249 on 04/07/2023
Meter calibration info not conspicuously posted**



**Photo # 6913 From Inspection 708900405 on 05/04/2023
Meter calibration info not conspicuously posted**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



Photo # 7404 From inspection 708900456 conducted on 05/10/2023 Meter calibration info not conspicuously posted



Photo # 9014 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



Photo # 9015 Meter calibration info not conspicuously posted



Photo # 9016 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



Photo # 4546 From Inspection 708900249 on 04/07/2023
Meter calibration info not conspicuously posted



Photo # 6914 From Inspection 708900405 on 05/04/2023
Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



Photo # 7406 From inspection 708900456 conducted on 05/10/2023 Meter calibration info not conspicuously posted



Photo # 9017 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 94-21 Pad

Location ID: 335210



Photo # 9018 Meter calibration info not conspicuously posted



Photo # 9019 Meter calibration info not conspicuously posted