

Inspection Photos
Location Name: BETHYL GW /29-12
Location #: 431798



Photo #1

Bethyl GW 29-12 (123-36782) Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: 2ndry plugs



Photo #2

Bethyl GW 29-12 Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: 2ndry plugs
Cementing units

Inspection Photos
Location Name: BETHYL GW /29-12
Location #: 431798



Photo #3
Bethyl GW 29-12 Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: 2ndry plugs
Site safety signage




Photo #4
Bethyl GW 29-12 Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: 2ndry plugs
JSA: 2023-05-30

Inspection Photos
Location Name: BETHYL GW /29-12
Location #: 431798



Photo #5

Bethyl GW 29-12 Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: 2ndry plugs
Wellsite access road



Photo #6

Bethyl GW 29-12 Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: 2ndry plugs
Wellsite sign

Inspection Photos

Location Name: BETHYL GW /29-12

Location #: 431798



Photo #7

Bethyl GW 29-12 Battery site

Plugged & Abandoned | PA

Plugging Ops: Cementing: 2ndry plugs

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources