

# Inspection Photos

API: 071-09011

Operator: WAPITI OPERATING LLC

Inspection Date: 5/30/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09011 | Date: 5/30/2023

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There are numerous noxious weeds along the access road that have not been controlled. The red arrow points to List B noxious weed - Houndstongue.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 5/30/2023



## Inspection Photos



**Photo 2.** There are numerous noxious weeds along the access road that need to be controlled. The red arrows points to List B noxious weed - Houndstongue.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 5/30/2023



## Inspection Photos



**Photo 3.** Further along the access road. There are numerous noxious weeds along the access road that need to be controlled. The red arrows points to List B noxious weed – Houndstongue and Field bindweed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09011 | Date: 5/30/2023



## Inspection Photos



**Photo 4.** Facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 5/30/2023

## Inspection Photos



**Photo 5.** There are numerous noxious weeds at the location that need to be controlled. The red arrow points to List B noxious weed - Houndstongue.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 5/30/2023