

# Inspection Photos

API: 071-09050

Operator: WAPITI OPERATING LLC

Inspection Date: 5/30/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There are numerous noxious weeds along the access road that have not been controlled. The red arrow points to List B noxious weed - Houndstongue.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023



## Inspection Photos



**Photo 2.** There are numerous noxious weeds along the access road that need to be controlled. The red arrows points to List B noxious weed - Houndstongue.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023

## Inspection Photos



**Photo 3.** Facing northeast toward the wellsite. There is vehicle rutting at the location which is not stabilized to prevent vehicle tracking.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023



## Inspection Photos



**Photo 4.** There are numerous noxious weeds at the location that need to be controlled. The red arrow points to List B noxious weed - Houndstongue.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023



## Inspection Photos



**Photo 5.** There are numerous noxious weeds at the location that need to be controlled. The red arrow points to List B noxious weed – Canada thistle.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023



## Inspection Photos



**Photo 6.** The guy line anchor marker has fallen over.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023



## Inspection Photos



**Photo 7.** There are numerous noxious weeds at the location that need to be controlled. The red arrow points to List B noxious weed – Houndstongue.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023



## Inspection Photos



**Photo 8.** The wellhead is leaking and there are stained soils.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09050 | Date: 5/30/2023