

Interim Reclamation and Stormwater Inspection

Date: 05/26/2023

Operator: VERDAD RESOURCES LLC -10651

Location ID: 432694

Inspection Document #: 708200282

Weld County, CO

NENE Section 35 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 1. It appears the Operator is using this location for equipment storage (e.g. vertical tanks, trucks w/ fracking equipment). All equipment will need to be removed immediately.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 3. Topsoil stockpiles are predominantly bare soil with no evidence of uniform vegetation cover. Undesirable vegetation (e.g. kochia) was also observed growing in portions of the topsoil stockpile. Additional reclamation activities are required.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 4. See comments in Photo 3.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 5. Stormwater BMPs do not appear to be properly functioning as stormwater is pooling throughout the location and leading to unstabilized production areas. Additionally, berm BMPs around the location are breached, have equipment parked on them, and are stained with apparent hydrocarbons.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 6. See comments in Photo 5. Hydrocarbon stained berm material pictured.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 7. See comments in Photo 5.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 8. See comments in Photo 5.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 9. See comments in Photo 5.