

Final Reclamation and Stormwater Inspection

Date: 05/26/2023

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 450097

Inspection Document #: 708200285

Weld County, CO

NWSW Section 27 T10N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Razor 27KW Pad
Location ID: 450097



Photo 1. Facing north from the proposed location. Photo illustrates that no disturbance was detected and the location does not appear to have been constructed.

Inspection Photos
Location Name: Razor 27KW Pad
Location ID: 450097



Photo 2. T posts and wooden stakes remain on location and are now considered debris. All debris will need to be removed in order to meet Rule 1004 standards.

Inspection Photos
Location Name: Razor 27KW Pad
Location ID: 450097



Photo 3. See comments in Photo 2.