

Final Reclamation and Stormwater Inspection

Date: 05/26/2023

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 450096

Inspection Document #: 708200287

Weld County, CO

NESW Section 27 T10N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Razor 27JW Pad
Location ID: 450096



Photo 1. This location does not comply with Rule 1004. Operator submitted a Form 4 Sundry Notices stating the above wells were not drilled. Location was not constructed at the proposed well location based off field observations. However, during this inspection, Staff observed that t posts and wooden stakes remain on location, which is now considered debris, and will need to be removed in order to meet Rule 1004 standards.

Inspection Photos
Location Name: Razor 27JW Pad
Location ID: 450096



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Razor 27JW Pad
Location ID: 450096



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Razor 27JW Pad
Location ID: 450096



Photo 4. See comments in Photo 1.