

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Entrance to location



Wellhead sign

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916




Sign at tank battery



Debris

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Debris



Open to wildlife

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Debris



Stained soil

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916




Stained soil



Staining. Unused equipment

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Stained soil from leaking equipment



Stained soil from leaking equipment

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916




Equipment leaks. Equipment in service?



Stained soils

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Soil staining



Tank overflow

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Stained soil from overflowed tank



Equipment leak and staining



Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Staining



Staining

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Excavated soil pile



Wattle failing

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Location view from Northwest corner



Location view from Southwest corner

Peakview Operatin Company LLC
Vososhin-Morton 1
Location #312916



Location view from Southeast corner



Location view from Northeast corner