

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Crow Valley 7-62-22 2H

Loc ID: 428324

Inspection: 696304826



Exhibit A

CA: Stained Soil at Gas Engine; See photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Identified stained soil at the Gas Engine has been properly addressed. Operator has disposed of stained soil and replaced it with fresh soil to comply with Rule 905.e.