

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Randall Creek 1-28H

Loc ID: 416391

Inspection: 696304904




Exhibit A

CA: Stained Soil at Wellhead. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Identified stained soil at the Wellhead has been properly addressed. The Operator has disposed of stained soil and cleaned up the area to comply with Rule 905.e.