

The image shows two circular, rusted metal rings lying on a dark, textured surface. The rings are heavily corroded, with a thick layer of orange-brown rust covering most of their surfaces. They are positioned in the center of the frame, with one ring partially overlapping the other. The background is a dark, possibly black or dark grey, material with some lighter, yellowish-brown spots and a visible seam or joint running horizontally across the upper portion of the image. A small metal fastener is visible at the top center, and another one is partially visible on the left side. In the bottom right corner, a portion of a metal rim is visible, with some faint markings that appear to be 'S 7000 7100'.

06/01/2023 11:26
N 40° 42' 47", W 104° 3' 13"
53000–53086 County Road 100
Grover CO 80729
United States
Pawnee National Grassland
Shull 35