

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403336021

Date Received:

06/01/2023

Spill report taken by:

YOUNG, ROB

Spill/Release Point ID:

481754

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>FUNDARE RESOURCES OPERATING COMPANY LLC</u>	Operator No: <u>10773</u>	Phone Numbers
Address: <u>5251 DTC PKWY STE 950</u>		Phone: <u>(303) 910-4511</u>
City: <u>GREENWOOD VILLAGE</u>	State: <u>CO</u>	Zip: <u>80111</u>
Contact Person: <u>Sydney Smith</u>		Mobile: <u>()</u>
		Email: <u>ssmith@fundareresources.com</u>

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402982788

Initial Report Date: 03/12/2022 Date of Discovery: 03/11/2022 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR NESW SEC 26 TWP 10N RNG 58W MERIDIAN 6Latitude: 40.809358 Longitude: -103.837000Municipality (if within municipal boundaries): _____ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Reference Location:

Facility Type: TANK BATTERY☒ Facility/Location ID No 435421Spill/Release Point Name: Razor 26 CPB☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): UnknownEstimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: 0-30 DegreesSurface Owner: FEE

Other(Specify): _____

<p>A produced water release occurred from the subject location on 3.11.2022. The cause of the spill was due to internal corrosion on the dump line. Upon discovery of the release on the line at the tank battery, all wells were shut in to the battery, and treater lines were drained. A crew was dispatched to the location to begin Hydrovac-ing, and excavation to remove the source and to eliminate impacts from migrating on-site.</p>

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
3/12/2022	CPW	Brandon Marette	-	Pending
3/12/2022	Timbro		-	Pending
3/12/2022	Weld County	Jason Maxey	-	Submitted

Rule 912.b.(1) Report to the Director (select all criteria that apply):	
Yes	<p>Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.</p> <p>Waters of the State: _____ Public Water System: _____ n/a</p> <p>Residence or Occupied Structure: _____ n/a Livestock: _____ n/a</p> <p>Wildlife: Threatened to Impact _____ Publicly-Maintained Road: _____ n/a</p>
No	<p>Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.</p>
No	<p>Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.</p>
No	<p>Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak</p> <p>Enter the approximate time of discovery _____ (HH:MM)</p> <p>Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____</p> <p>Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____ No</p> <p>Enter the Document Number of the Initial Accident Report, Form 22 _____</p> <p>Was there damage during excavation? _____ No</p> <p>Was CO 811 notified prior to excavation? _____</p>
No	<p>Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.</p> <p>Estimated Volume of Impacted Solids (cu. yd.): _____</p>
No	<p>Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:</p> <p><input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water</p> <p><input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater</p> <p><input type="checkbox"/> The presence of contaminated soil in contact with Groundwater</p> <p><input type="checkbox"/> The presence of contaminated soil in contact with Surface water</p>

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 06/01/2023		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>35</u>		Width of Impact (feet): <u>30</u>	
Depth of Impact (feet BGS): <u>10</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
The extent of the impacts was determined with confirmation soil samples that were collected in accordance with COGCC 915 guidance, and were analyzed for full table 915 constituents.			
Soil/Geology Description:			
Silty sand, silstone			
Depth to Groundwater (feet BGS) <u>38</u>		Number Water Wells within 1/2 mile radius: <u>9</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>1195</u>	None <input type="checkbox"/>	Surface Water _____ None <input checked="" type="checkbox"/>
	Wetlands _____	None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
	Livestock _____	None <input checked="" type="checkbox"/>	Occupied Building _____ None <input checked="" type="checkbox"/>
Additional Spill Details Not Provided Above:			
There are no residents or habitable structures within a quarter mile of the release. There are no marked county roads, however there is a lease road 122' North of the release location. There is no marked surface water within a quarter mile of the release, but there is a dry ravine 917' to the South of the release. There are 2 Monitoring wells 1311' East of the release location. The release is within the buffer of the Mule Deer Severe winter range, CPW has been notified of this.			

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 06/01/2023

Root Cause of Spill/Release Corrosion

Other (specify) _____

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Dump line

Describe Incident & Root Cause (include specific equipment and point of failure)

The root cause of the spill was due to internal corrosion at the 6 o'clock position on the dump line. Upon discovery of the release on the line at the tank battery, all wells were shut in to the battery, and treater lines were drained. A crew was dispatched to the location to begin Hydrovacing, and excavation to remove the source and to eliminate impacts from migrating on-site.

Describe measures taken to prevent the problem(s) from reoccurring:

The line was repaired/replaced to ensure the issue does not occur again.

Volume of Soil Excavated (cubic yards): 388

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal ☐ Onsite Treatment ☐ Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure:
- ☐ Corrective Actions Completed (documentation attached, check all that apply)
 - ☐ Horizontal and Vertical extents of impacts have been delineated.
 - ☐ Documentation of compliance with Table 915-1 is attached.
 - ☐ All E&P Waste has been properly treated or disposed.
 - ☒ Work proceeding under an approved Form 27 (Rule 912.c).
 - Form 27 Remediation Project No: 29346
 - ☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

All previous COAs have been addressed, and this form has been submitted to close out the form 19 and move it to remediation project number 29346. All remediation site progress and updates will be provided in supplemental form 27s.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Sydney Smith

Title: Director EHSR Date: 06/01/2023 Email: ssmith@fundareresources.com

COA Type	Description
0 COA	

Attachment List

Att Doc Num

Name

403420321	SITE MAP
403420323	TOPOGRAPHIC MAP

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)