

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 111 Pad

Location ID: 322441



Photo # 9125 From entrance to location



Photo # 9126 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 111 Pad

Location ID: 322441



Photo # 9127 Location



Photo # 9128 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 111 Pad

Location ID: 322441



Photo # 4862 From Inspection 708900254 conducted on 04/10/2023 Meter calibration info not conspicuously posted



Photo # 9132 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 111 Pad
Location ID: 322441



Photo # 9131 Meter calibration info not conspicuously posted