

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



Photo # 9181 From entrance to location



Photo # 9182 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



Photo # 9183 Location



Photo # 9184 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



Photo # 9185 Location



Photo # 7020 From Inspection 708900411 conducted on 05/05/2023 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



Photo # 9186 Meter calibration info not conspicuously posted



Photo # 9187 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad
Location ID: 335283



Photo # 7019 From Inspection 708900411 conducted on 05/05/2023 Meter calibration info not conspicuously posted

Photo # 9188 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



Photo # 9189 Meter calibration info not conspicuously posted