

Final Reclamation Inspection

May 31, 2023

Operator: PHOENIX RESOURCES LLC - 10691

Location ID: 405223

Inspection Document #: 697504688

Weld County, CO

NENE Section 16 T8N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State #1
Location ID: 405223



Photo 1. Photo taken from the northern access road, facing South. The access road is evident and lacks any vegetation along portions. Due to the sandy soil, wind erosion has high potential and wind erosion was observed.



Photo 2. Photo taken along a central portion of the access road, facing South. See comments under Photo 1.

Inspection Photos
Location Name: State #1
Location ID: 405223



Photo 3. Photo taken along an eastern portion of the access road, facing South. See comments under Photo 1.



Photo 4. Photo taken from the location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: State #1
Location ID: 405223



Photo 5. Photo taken from the location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: State #1
Location ID: 405223



Photo 6. Photo taken from the location illustrating debris left on location.



Photo 7. Reference photo taken east of the location, facing East.