

**Inspection Photos**  
**Location Name: Johnson C29-03 Pad**  
**Location ID: 460293**



**Photo #1 Cattle Guard packed with mud**

**Photo #2 Cattle Guard packed with mud & Lease road needs maintained**

**Inspection Photos**  
**Location Name: Johnson C29-03 Pad**  
**Location ID: 460293**



**Photo #3 Cattle Guard packed with mud**

**Photo #4 Lease road needs maintained**

**Inspection Photos**  
**Location Name: Johnson C29-03 Pad**  
**Location ID: 460293**



**Photo #5 Lease road needs maintained**

**Photo #6 Lease road needs maintained**