

Inspection Photos
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



Photo # 9259 From entrance to location



Photo # 9260 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



Photo # 9263 Location



Photo # 9264 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



Photo # 9266 Location



Photo # 9267 Hole in the ground - Wildlife/personnel hazard