



Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #1 facility 120692 overview photo.





Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #2 hydro excavation to expose trench for new line.



Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #3 hydro excavation to expose trench for new line.





Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #4 . It is understood this is the area where a sheen appeared on the excavation water. Visually impacted soils should be removed and disposed of as E&P waste.



Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #5 Area where some of the overburden from the excavation were placed, just south of facility on pad. The area where hydrocarbon was detected was reportedly disposed of at an approved E&P waste facility. The black marks on surface seen in photo appear when the surface is scuffed. This overburden pile should be sampled for Table 915-1.





Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #6 looking north. The excavation can be seen going from left to right in photo. To the left of the photo is the dehy that is to be piped with the new trench.



Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #7 area near Dehy.



Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #8 standing near the dehy looking east. It was reported that the water in the ditch is due to rain the previous day.





Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #9 building where hydrocarbon was observed in the hydro excavated trench.





Inspection Photos
Spill 484529
Location 120692
Inspection
Date:5/30/2023

All Photos taken
by Kris Neidel

Photo #10 overview photo, looking northeast.

