

# Inspection Photos

API: 055-06037

Operator: OXY USA INC

Inspection Date: 6/1/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06037 | Date: 6/1/2023

## Inspection Photos



**Photo 1.** There has been grading performed along the road however, gravel material has been pushed off the road causing additional disturbance This material needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06037 | Date: 6/1/2023

## Inspection Photos



**Photo 2.** There has been grading performed along the road however, gravel material has been pushed off the road causing additional disturbance. This material needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06037 | Date: 6/1/2023

## Inspection Photos



**Photo 3.** Facing southeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06037 | Date: 6/1/2023