



Inspection Photos  
Well 081-05710  
Inspection  
Date:5/30/2023

All Photos taken  
by Kris Neidel

Photo #1 sign at entry of location.



**Photo #2 overview of location.**

Inspection Photos  
Well 081-05710  
Inspection  
Date:5/30/2023

All Photos taken  
by Kris Neidel



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





**Photo #3 wellhead**

**Inspection Photos  
Well 081-05710  
Inspection  
Date:5/30/2023**

**All Photos taken  
by Kris Neidel**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo #4 looking north at AGT.

Inspection Photos  
Well 081-05710  
Inspection  
Date:5/30/2023

All Photos taken  
by Kris Neidel



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Well 081-05710  
Inspection  
Date:5/30/2023

All Photos taken  
by Kris Neidel

**Photo #5 some trash on location, rubber seen on right of photo.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Well 081-05710  
Inspection  
Date:5/30/2023

All Photos taken  
by Kris Neidel

Photo #6 staining on side of tank from overtopping.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources