

Inspection Photos
Location Name: CAERUS PICEANCE LLC C8E Pad
Location ID: 334799



Photo # 9304 From entrance to location



Photo # 9305 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC C8E Pad
Location ID: 334799



Photo # 9306 Location



Photo # 9307 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC C8E Pad
Location ID: 334799



Photo # 9391 Valve on production tank leaking fluid



Photo # 9414 Valve on production tank leaking fluid

Inspection Photos
Location Name: CAERUS PICEANCE LLC C8E Pad
Location ID: 334799



Photo # 9438 Valve on production tank leaking fluid



Photo # 9439 Valve on production tank leaking fluid

Inspection Photos
Location Name: CAERUS PICEANCE LLC C8E Pad
Location ID: 334799



Photo # 9443 Debris



Photo # 9444 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC C8E Pad
Location ID: 334799



Photo # 9445 Debris



Photo # 9309 Debris



Inspection Photos
Location Name: CAERUS PICEANCE LLC C8E Pad
Location ID: 334799



Photo # 9451 Bradenhead hooked into flowline, no check valve observed



Photo # 9452 Bradenhead hooked into flowline, no check valve observed