

Inspection Photos
Location Name: CAERUS PICEANCE LLC P6 Pad
Location ID: 334913



Photo # 9473 From entrance to location



Photo # 9474 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC P6 Pad
Location ID: 334913



Jun 5, 2023 at 10:38:54 AM
CO



Jun 5, 2023 at 10:42:05 AM
CO

Photo # 9475 Location

Photo # 9479 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC P6 Pad
Location ID: 334913



Photo # 9480 Location



Photo # 9414 Hole in flowline heating insulation/wildlife hazard