

Interim and Stormwater Inspection

June 1, 2023

Operator: KP Kauffman Company Inc # 46290

Location ID: 478086

Inspection Document #:709400213

Weld, County

SESE, Section 29, 1N67W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRR 43 PAN AM G Consolidation 2

Location ID: 478086



Photo 1. Photo taken of stormwater erosion along country road onto site.



Photo 2. See photo 1 comments.

Inspection Photos

Location Name: UPRR 43 PAN AM G Consolidation 2

Location ID: 478086



Photo 3. Photo taken of sediment accumulation from stormwater flowing over the site.



Photo 4. Photo taken of damaged/improperly installed BMP's.

Inspection Photos
Location Name: UPRR 43 PAN AM G Consolidation 2
Location ID: 478086



Photo 5. See photo 4 comments.



Photo 6. Photo taken of proximity of site to wetland area.