

Interim and Stormwater Inspection

June 1, 2023

Operator: KP Kauffman Company Inc # 46290

Location ID: 483852

Inspection Document #:709400214

Weld, County

NENE, Section 6, 1N68W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Koch Tank Battery

Location ID: 483852



Photo 1. Photo taken of Excavated spill area onsite.



Photo 2. Photo taken of exclusionary fence with large tears in it and where stormwater is running into the excavation from the site.

Inspection Number: 7094001214

Inspection Photos
Location Name: Koch Tank Battery
Location ID: 483852



Photo 3. See photo 2 comments..



Photo 4. Photo taken of exclusionary fence down and where stormwater has flowed into the excavation from the site.

Inspection Number: 7094001214

Inspection Photos
Location Name: Koch Tank Battery
Location ID: 483852



Photo 5. Photo of poorly installed exclusionary fence around excavation.



Photo 6. Photo of stormwater erosion leading off of location into wetland area.

Inspection Number: 7094001214

Inspection Photos
Location Name: Koch Tank Battery
Location ID: 483852



Photo 7. Photo of weeds on site.



Photo 8. Photo of fill slope berm constructed of crushed concrete.

Inspection Number: 7094001214

Inspection Photos
Location Name: Koch Tank Battery
Location ID: 483852



Photo 9. See photo 8 comments.



Photo 10. Photo of crushed concrete on fill slope.