

Inspection Photos
Location Name: LARDISON 42-18
Location ID: 320210



Photo# 1 Tanks.



Photo# 2 Separator.

Inspection Photos
Location Name: LARDISON 42-18
Location ID: 320210



Photo# 3 Well head.



Photo# 4 leak at well head.