

Inspection Photos
Location Name: Kettl 23-3
Location ID: 331636



Photo 1 – Wildlife netting and Labels missing



Photo 2 – Wildlife netting and Labels missing

Inspection Photos
Location Name: Kettl 23-3
Location ID: 331636



Photo 3 – Compressor



Photo 4 – Labels missing

Inspection Photos
Location Name: Kettl 23-3
Location ID: 331636



Photo 5 – Well Sign



Photo – Wellhead

Inspection Photos
Location Name: Kettl 23-3
Location ID: 331636



Photo 7 – Label Missing