

# Inspection Photos

May 30, 2023

Operator: CAERUS PICEANCE LLC - #10456

Location ID: 311645

Location Name: GMR/8-6 (K8W)

Inspection Document #: 702801572

Garfield County, CO

NESW Section 8 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GMR/8-6 (K8W)  
Location ID: 311645



**Photo 1.** Photo taken from the south shows an overview of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801572

Inspection Photos  
Location Name: GMR/8-6 (K8W)  
Location ID: 311645



Photo 2. Photos show production areas.



Inspection Photos  
Location Name: GMR/8-6 (K8W)  
Location ID: 311645



**Photo 3.** Photo shows stained soil at a wellhead.



Inspection Photos  
Location Name: GMR/8-6 (K8W)  
Location ID: 311645



**Photo 4.** Photos show musk thistle, a List B Noxious weed in the western interim area, particularly common around the stormwater ditch.

Inspection Photos  
Location Name: GMR/8-6 (K8W)  
Location ID: 311645



Photo 5. Photos show interim areas to the east (left), south (right) and west (center) are vegetated with perennial grasses.



Inspection Photos  
Location Name: GMR/8-6 (K8W)  
Location ID: 311645



**Photo 6.** Photo shows the reference area vegetation community to the south of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801572