

Inspection Photos
Location Name: Booth USX EE25-11D Pad
Location ID: 425393



Photo 1: Wellhead Sign



Photo 2: Equipment removed

Inspection Photos
Location Name: Booth USX EE25-11D Pad
Location ID: 425393




Photo 3: Equipment removed




Photo 4: Meter not calibrated