

**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Entrance to location**



**Sign entering location. No tank battery sign**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Unidentified tank missing required labels**



**Open to wildlife**

**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Unused equipment. Debris**



**Debris. Stained soil**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Open to wildlife**



**Unidentified tank missing required labels**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Unused equipment.**



**Debris**





**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Debris**



**Unmarked anchor**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Wellhead sign on the ground missing required information**



**Unused equipment**

**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Stacks open to wildlife. Unused equipment.**



**Open to wildlife**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Open to wildlife. Containment integrity?**



**Debris. Stained soil**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**




**Bird protector**



**Missing wildlife protection**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Stained soil**



**Open end tank valve. Stained soil**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Location from Southwest corner**



**Location from Northwest corner**



**Antler Energy LLC  
Martin-Government 1 (14-8)  
Location #312935**



**Location from Northeast corner**



**Location from Southeast corner**