

Inspection Photos

May 30, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334747

Location Name: SAVAGE-67S94W/1NENE

Inspection Document #: 702801577

Garfield County, CO

NENE Section 1 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 1. Photo taken from the east shows an overview of the location.



Inspection Photos

Location Name: SAVAGE-67S94W/1NENE

Location ID: 334747



Photo 2. Photo shows impacted fluid within the methanol tank secondary containment has been removed and holes in the wire mesh wildlife protection BMP have been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801577

Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 3. Photo shows untreated spotted knapweed (List B Noxious) in the eastern interim area.



Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 4. Photos show untreated (green) spotted knapweed plants directly next to treated (red) knapweed plants.



Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 5. Photo shows an example of interim areas to the south.

