

Inspection Photos

May 30, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334572

Location Name: SAVAGE-67S94W/1NESE

Inspection Document #: 702801579

Garfield County, CO

NESE Section 1 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 1. Photos taken from the north shows an overview of the location.

Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 2. Photo shows the access road directly to the north of the location.



Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572




Photo 3. Photos show spotted knapweed at the southeast of the location, just outside the perimeter fence but within the location disturbance. Photo left taken during the previous inspection. Photo right taken during the current inspection. Plants are untreated.

Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 4. Photos show spotted knapweed in the southeast interim area. Photo left shows an untreated plant. Photo right shows treated (red) directly next to untreated (green) plants.

