

Inspection Photos
Location Name: CAERUS PICEANCE LLC 07EB Pad
Location ID: 334883



Photo # 9501 From entrance to location



Photo # 9502 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC 07EB Pad

Location ID: 334883



Jun 5, 2023 at 11:21:54 AM
CO



Jun 5, 2023 at 11:23:40 AM
CO

Photo # 9503 Location

Photo # 9506 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC 07EB Pad
Location ID: 334883



Photo # 9507 Location



Photo # 9504 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC 07EB Pad
Location ID: 334883



Photo # 9505 Debris



Photo # 9508 Unmarked deadman

Inspection Photos
Location Name: CAERUS PICEANCE LLC 07EB Pad
Location ID: 334883



Photo # 9521 Unmarked deadman



Photo # 9523 Same unmarked deadman from a different angle