

Operator: 8 NORTH LLC
Location Name: HAYNES 1062-1-11
Loc ID: 417297
Inspection: 696304933



Exhibit A

CA: Oil Tank - Content has faded no longer visible. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Label on Oil Tank has been replaced with a new one. The Operator has been notified of Rule 905.e. regarding treatment/disposal of oily waste and Land Treatment requirements. Location will be maintained to comply with Rule 905.e.



Exhibit A

CA: Unmarked Riser at Heater Treater; Comply with Rule 606.

CA Resolution: Identified Riser at Heather Treater has now been appropriately marked to comply with Rule 606.