

Inspection Photos

API: 055-06201

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/6/2023

Inspection Photos



Photo 1. Facing west toward the location. There is mostly bare ground at the location and a reduction in noxious weeds was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/6/2023

Inspection Photos



Photo 2. Facing east toward the location. There is mostly bare ground at the location and a reduction in noxious weeds was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/6/2023

Inspection Photos



Photo 3. There is still some Field bind weed found on location. Other noxious were not observed at the time of inspection..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/6/2023

Inspection Photos



Photo 4. Facing west toward the surrounding undisturbed reference area which consists of desirable vegetation Western wheat grass, Smooth brome among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/6/2023