

Inspection Photos

API: 055-06279

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 6/6/2023

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 6/6/2023

Inspection Photos



Photo 2. Facing northwest toward the cut slope which is bare of vegetation and not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 6/6/2023

Inspection Photos



Photo 3. There is rubber hose stick out of the ground along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 6/6/2023

Inspection Photos



Photo 4. Facing east at the location. There are areas that have not established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 6/6/2023