

Inspection Photos

API: 055-06194

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06194 | Date: 6/6/2023

Inspection Photos



Photo 1. Facing south toward the access road. There is sparse vegetation along this area of the reclaimed and there are some noxious weeds (Field bindweed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/6/2023

Inspection Photos



Photo 2. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/6/2023

Inspection Photos



Photo 3. There are areas of the location that are bare of vegetation growth.



Inspection Photos



Photo 4. Facing northeast at the west side of the location. The desirable vegetation has not re-established and there are noxious weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/6/2023

Inspection Photos



Photo 5. Center of the location facing north. The perennial vegetation has not established to 80% levels



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/6/2023