

Inspection Photos

API: 055-06212

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06212 | Date: 6/6/2023

Inspection Photos



Photo 1. This photo was taken from a distance showing the location still remains. The landowner is storing equipment on location. If the landowner wishes for the location to remain then a variance must be submitted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/6/2023

Inspection Photos



Photo 2. The is photo was taken during previous inspection. Facing west toward the location. The location was never recontoured and reclaimed. The surface owner is using the location for a storage area.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06212 | Date: 6/6/2023

Inspection Photos



Photo 3. The is photo was taken during previous inspection. There are noxious weeds at the location which include Cheat grass, Red stem filaree, Field bind weed, and Jointed Goat grass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/6/2023

Inspection Photos



Photo 4. . The is photo was taken during previous inspection. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/6/2023