

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork D09A 696 Pad

Location ID: 335560



Photo # 9880 From entrance to location



Photo # 9881 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork D09A 696 Pad

Location ID: 335560



Photo # 9882 Location



Photo # 9883 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork D09A 696 Pad

Location ID: 335560



Photo # 9885 Location



Photo # 9886 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork D09A 696 Pad

Location ID: 335560



Photo # 9888 Location



Photo # 9624 Line connected to wellhead leaking/stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork D09A 696 Pad

Location ID: 335560



Photo # 9891 Line connected to wellhead leaking/stained soils & gravel



Photo # 9900 Line connected to wellhead leaking/stained soils & gravel