

# Interim and Stormwater Inspection

May 15, 2023

Operator: Poncho Production Co # 71450

Location ID: 320629

Inspection Document #:709400220

Arapahoe, County

SWSW, Section 27, 4S60W

Reed Wold

Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DTA-Peoria  
Location ID: 483852



Photo 1. Photo taken of location sign..

Photo 2. Photo taken of weeds and vegetation in tank battery secondary containment.



**Inspection Photos**  
**Location Name: DTA-Peoria**  
**Location ID: 320629**



**Photo 1. Photo taken of location tank battery.**

**Photo 2. Photo taken of well head and weeds onsite.**