

# Interim and Stormwater Inspection

May 15, 2023

Operator: Tyler Rockies Exploration # 41550

Location ID: 320719

Inspection Document #:709400222

Arapahoe, County

SWNE, Section 6, 4S59W

Reed Wold

Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Linnebur Tank Battery  
Location ID: 320719



Photo 1. Photo taken of location sign.



Photo 2. Photo taken of weeds on site.



Inspection Photos  
Location Name: Linnebur Tank Battery  
Location ID: 320719



Photo 3. Photo taken of location tank battery.



Photo 4. Photo taken of cheatgrass on location

Inspection Photos  
Location Name: Linnebur Tank Battery  
Location ID: 320719



**Photo 5. Photo taken of stained area and leaking valve on combustor on site.**



**Photo 6. Photo taken of unlined pit onste.**

Inspection Number: 7094001222



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources