

Interim and Stormwater Inspection

May 17, 2023

Operator: GMT Exploration Company # 10243

Location ID: 478811

Inspection Document #:709400227

Elbert, County

SENW, Section 10, 6S64W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Vulcan Tank Battery
Location ID: 478811



Photo 1. Photo taken of access road bar ditch full of sediment.

Photo 2. Photo taken of trackout onto Co road 194 from access road



Inspection Photos
Location Name: Vulcan Tank Battery
Location ID: 478811



Photo 3. Photo taken of runoff path going around rock check dams on access rd to site.



Photo 4. Photo taken of erosion along access road to site, due to improper soil stabilization.

Inspection Photos
Location Name: Vulcan Tank Battery
Location ID: 478811



Photo 5. Photo taken of access road culvert inlet. no rip rap present. erosion and lack of proper soil stabilization.



Photo 6. Photo taken of erosion coming off access road slope, BMP failure, erosion and reeling of roadside.



Inspection Photos
Location Name: Vulcan Tank Battery
Location ID: 478811



Photo 7. Photo taken of access road culvert outlet, sediment burning by water lines, and sediment has moved offsite.



Photo 8. Photo taken of erosion coming off location due to the corner of the pad collapsing.



Inspection Photos
Location Name: Vulcan Tank Battery
Location ID: 478811



Photo 9. See Photo 8 Comments.

Photo 10. See photo 8 comments

Inspection Photos
Location Name: Vulcan Tank Battery
Location ID: 478811



Photo 11. Photo of pad corner berm collapse.

Photo 12. Photo of reeling under BMP on fill slope of location.

Inspection Photos
Location Name: Vulcan Tank Battery
Location ID: 478811



Photo 13. Photo of weeds on perimeter of location.



Photo 14. Photo of topsoil stockpile. weeds and bare soil present.

