

Final Reclamation Inspection

May 22, 2023

Operator: Renegade Oil & Gas # 74165

Location ID: 319860

Inspection Document #:709400233

Adams, County

NWNW, Section 20, 2S64W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 1. Photo taken of location sign.

Photo 2. Photo of weeds and debris on location.

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 3. Photo taken of erosion on site and access road.



Photo 4. Photo of dumped trash on location.