

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork E09 696 Pad

Location ID: 335856



Jun 8, 2023 at 11:00:17 AM



Jun 8, 2023 at 11:01:09 AM
CO

Photo # 9754 From entrance to location

Photo # 9755 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork E09 696 Pad

Location ID: 335856



Photo # 9756 Location



Photo # 9757 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork E09 696 Pad

Location ID: 335856



Photo # 9758 Location



Photo # 9759 Stained soils & gravel



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute Middle Fork E09 696 Pad

Location ID: 335856



Photo # 9762 Stained soils & gravel



Photo # 9767 Wildlife hazard/open ended Kelly hose