

**Operator: CIVITAS NORTH**  
**Location Name: Hunt Fed 8-60 6A**  
**Loc ID: 454627**  
**Inspection: 708200160**



**Exhibit A**



**Exhibit B**





**Exhibit C**



**Exhibit D**



**Exhibit E**

**CA:** This location does not comply with Rule 1003. During this inspection, it was observed that the interim areas consist predominantly of bare soil with little germination of desirable plant species present. Undesirable plant species were also detected, including Russian thistle and kochia. It also appears that the northern production areas, around the wells, have not been reclaimed with approximately 1.8 acres of unused production pad observed. If the Operator is not going to commence additional drilling activities (7 wells w/expired permits) then the production area identified in the inspection photos shall be reclaimed. Refer to attached inspection photos for additional information. Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil and continue to monitor and manage this site until the location meets Rule 1003 standards. CA date is the date the location was observed out of compliance.

**CA Resolution:** Operator has reported that the location has been re-seeded to establish vegetation and to comply with Rule 1003.