

**TEP**  
**North Bank B**  
**Location # 311621**



**ECD and separators**



**Tank battery**





TEP  
North Bank B  
Location # 311621



**Meter calibration card not conspicuously posted.**



**Meter calibration card not conspicuously posted.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
North Bank B  
Location # 311621



Battery signage



Tank battery





TEP  
North Bank B  
Location # 311621



Open cellars



Open cellars



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
North Bank B  
Location # 311621



**Previous inspection photo of holes in containment  
document # 700704664**



**Recent inspection of holes in containment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
North Bank B  
Location # 311621



**Previous inspection photo of holes in containment  
document # 700704664**



**Recent inspection of holes in containment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
North Bank B  
Location # 311621



Recent inspection of holes in containment



Recent inspection of holes in containment



TEP  
North Bank B  
Location # 311621



**Staining from previous inspection document #  
700704664**



**Recent photo of staining**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**TEP**  
**North Bank B**  
**Location # 311621**



**Staining from previous inspection document #  
700704664**



**Recent photo of staining**





**TEP**  
**North Bank B**  
**Location # 311621**



**Staining out side of containment**



**Staining out side of containment**





TEP  
North Bank B  
Location # 311621



Staining



Debris



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources