

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

01/31/2022

Document Number:

402942711

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

### Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

### Operator Information

OGCC Operator Number: 10352 Contact Person: Jacob Harter  
Company Name: CM PRODUCTION LLC Phone: (970) 946-3761  
Address: 390 UNION BLVD SUITE 620 Fax: ( )  
City: LAKEWOOD State: CO Zip: 80228 Email: jharter@cottonwoodconsulting.com

### Identification Information

API Number: 05 -   -   OGCC Facility ID: 324634 Initial Form 19 or 27 Document number: 402673506  
Facility Name: MARGARET SPAULDING-69N81W Facility Number: 28SWSE Facility Type: LOCATION  
Location QtrQtr: SWSE Section: 28 Township: 9N Range: 81W Meridian:    
County: JACKSON Field Name: LONE PINE  
Federal, Indian or State Lease Number:

### Information Submitted By:

Company Name: CM PRODUCTION LLC Agent Name: Jacob Harter Title: Consultant  
Phone Number: 970-946-3761 Email: jharter@cottonwoodconsulting.com

### Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted

### Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 427281 Facility Name: M. SPAULDING CENTRALIZED TANK BATT 1 Facility Type:    
Location: QtrQtr: SWSE Sec: 28 Twp: 9N Range: 81W Meridian: 6  
County Name: JACKSON Latitude: 40.718009 Longitude: -106.498498

### Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 95044 Document Name: Size of file in bytes: 95232 File Name: M. Spaulding Centralized Tank Battery Soil Sample (15).xls  
SampleType:   Matrix:    
Facility ID: 427281 Sample ID: 632048 Sample Name: M. Spaulding Centralized Tank Battery SS15 Sample Date: 09/01/2021  
Collection Point: Soil Matrix: SOIL Pre Post: Remediation  
Project Number:   Remediation Number:   Complaint Number:   NOAV Number:    
Inspection Number:   Spill Number:   Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2109048-03

Batch ID: 95031	Document Name: Size of file in bytes: 93696	File Name: M. Spaulding Centralized Tank Battery Soil Sample (6).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632034	Sample Name: M. Spaulding Centralized Tank Battery SS06
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-06		
Batch ID: 95043	Document Name: Size of file in bytes: 95232	File Name: M. Spaulding Centralized Tank Battery Soil Sample (14).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632047	Sample Name: M. Spaulding Centralized Tank Battery SS14
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2109048-02		
Batch ID: 95029	Document Name: Size of file in bytes: 93696	File Name: M. Spaulding Centralized Tank Battery Soil Sample (4).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632032	Sample Name: M. Spaulding Centralized Tank Battery SS04
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-04		
Batch ID: 95036	Document Name: Size of file in bytes: 93184	File Name: M. Spaulding Centralized Tank Battery Soil Sample (8).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632040	Sample Name: M. Spaulding Centralized Tank Battery SS08
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-08		
Batch ID: 95028	Document Name: Size of file in bytes: 93696	File Name: M. Spaulding Centralized Tank Battery Soil Sample (3).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632031	Sample Name: M. Spaulding Centralized Tank Battery SS03
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-03		
Batch ID: 95047	Document Name: Size of file in bytes: 95232	File Name: M. Spaulding Centralized Tank Battery Soil Sample (18).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632051	Sample Name: M. Spaulding Centralized Tank Battery SS28
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2109048-06		

Batch ID: 95026	Document Name: Size of file in bytes: 93184	File Name: M. Spaulding Centralized Tank Battery Soil Sample (2).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632029	Sample Name: M. Spaulding Centralized Tank Battery SS02
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-02		
Batch ID: 95046	Document Name: Size of file in bytes: 95744	File Name: M. Spaulding Centralized Tank Battery Soil Sample (17).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632050	Sample Name: M. Spaulding Centralized Tank Battery SS17
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2109048-05		
Batch ID: 95030	Document Name: Size of file in bytes: 93696	File Name: M. Spaulding Centralized Tank Battery Soil Sample (5).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632033	Sample Name: M. Spaulding Centralized Tank Battery SS05
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-05		
Batch ID: 95041	Document Name: Size of file in bytes: 93184	File Name: M. Spaulding Centralized Tank Battery Soil Sample (12).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632045	Sample Name: M. Spaulding Centralized Tank Battery SS12
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-12		
Batch ID: 95024	Document Name: Size of file in bytes: 93184	File Name: M. Spaulding Centralized Tank Battery Soil Sample (1).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632027	Sample Name: M. Spaulding Centralized Tank Battery SS01
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-01		
Batch ID: 95033	Document Name: Size of file in bytes: 93696	File Name: M. Spaulding Centralized Tank Battery Soil Sample (7).xls
SampleType: _____		Matrix: _____
Facility ID: 427281	Sample ID: 632037	Sample Name: M. Spaulding Centralized Tank Battery SS07
Collection Point: Soil	Matrix: SOIL	Pre Post: Remediation
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Green Analytical Laboratories, Inc.
Lab Sample ID: 2108209-07		

Batch ID:	95038	Document Name:	Size of file in bytes: 93696	File Name:	M. Spaulding Centralized Tank Battery Soil Sample (9).xls
SampleType:		Matrix:			
Facility ID:	427281	Sample ID:	632042	Sample Name:	M. Spaulding Centralized Tank Battery SS09
Collection Point:	Soil	Matrix:	SOIL	Pre Post:	Remediation
Project Number:		Remediation Number:		Complaint Number:	
Inspection Number:		Spill Number:		Laboratory:	Green Analytical Laboratories, Inc.
Lab Sample ID:	2108209-09				
Batch ID:	95040	Document Name:	Size of file in bytes: 93696	File Name:	M. Spaulding Centralized Tank Battery Soil Sample (11).xls
SampleType:		Matrix:			
Facility ID:	427281	Sample ID:	632044	Sample Name:	M. Spaulding Centralized Tank Battery SS11
Collection Point:	Soil	Matrix:	SOIL	Pre Post:	Remediation
Project Number:		Remediation Number:		Complaint Number:	
Inspection Number:		Spill Number:		Laboratory:	Green Analytical Laboratories, Inc.
Lab Sample ID:	2108209-11				
Batch ID:	95045	Document Name:	Size of file in bytes: 95744	File Name:	M. Spaulding Centralized Tank Battery Soil Sample (16).xls
SampleType:		Matrix:			
Facility ID:	427281	Sample ID:	632049	Sample Name:	M. Spaulding Centralized Tank Battery SS16
Collection Point:	Soil	Matrix:	SOIL	Pre Post:	Remediation
Project Number:		Remediation Number:		Complaint Number:	
Inspection Number:		Spill Number:		Laboratory:	Green Analytical Laboratories, Inc.
Lab Sample ID:	2109048-04				
Batch ID:	95048	Document Name:	Size of file in bytes: 95744	File Name:	M. Spaulding Centralized Tank Battery Soil Sample (19).xls
SampleType:		Matrix:			
Facility ID:	427281	Sample ID:	632052	Sample Name:	M. Spaulding Centralized Tank Battery SS19
Collection Point:	Soil	Matrix:	SOIL	Pre Post:	Remediation
Project Number:		Remediation Number:		Complaint Number:	
Inspection Number:		Spill Number:		Laboratory:	Green Analytical Laboratories, Inc.
Lab Sample ID:	2109048-07				
Batch ID:	95042	Document Name:	Size of file in bytes: 95744	File Name:	M. Spaulding Centralized Tank Battery Soil Sample (13).xls
SampleType:		Matrix:			
Facility ID:	427281	Sample ID:	632046	Sample Name:	M. Spaulding Centralized Tank Battery SS13
Collection Point:	Soil	Matrix:	SOIL	Pre Post:	Remediation
Project Number:		Remediation Number:		Complaint Number:	
Inspection Number:		Spill Number:		Laboratory:	Green Analytical Laboratories, Inc.
Lab Sample ID:	2109048-01				
Batch ID:	95039	Document Name:	Size of file in bytes: 93696	File Name:	M. Spaulding Centralized Tank Battery Soil Sample (10).xls
SampleType:		Matrix:			
Facility ID:	427281	Sample ID:	632043	Sample Name:	M. Spaulding Centralized Tank Battery SS10
Collection Point:	Soil	Matrix:	SOIL	Pre Post:	Remediation
Project Number:		Remediation Number:		Complaint Number:	
Inspection Number:		Spill Number:		Laboratory:	Green Analytical Laboratories, Inc.
Lab Sample ID:	2108209-10				

**Sample Facility Attachment:**

No Facility Attachment

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	06/10/2023
Total: 1 comment(s)		