

Inspection Photos  
Seeley Sparo #1-36  
API 033-06091



**Photo #1. View of containment berm corrective action documented in FIR #712700064.**



**Photo #2. View of completed corrective action.**